

Lísted Buíldíngs

Homíngton

Homington Farmhouse

HOMINGTON VILLAGE (north side) Homington Farmhouse and attached farm buildings II Farmhouse with attached C19 farm buildings to rear. Mid-C18 with alterations of C19. Flemish bond brick, tiled roof, hipped to right, brick stacks. L-plan. 2-storey, 3-window front. Partly glazed door with fielded panels, in gabled brick porch to left of centre, to left and to right is 16-pane sash with margin lights, to right is blind segmental-arched window. 3-brick plat band to first floor, two 16-pane sashes with margin-lights, one 12-pane sash and one square blind window to right.

Right return is C19 rebuild, 16- pane sash and 3-light casement to ground floor, with 16-pane sash and leaded 3-light casement to first floor. Left return has lean- to against ground floor, vitrified brick lozenge decoration to first floor attic, has casement. Rear has C19 lean-to up to ground floor, one 2-light casement to first floor, to left is 2-storey wing rebuilt in mid-C19, with casements. Interior has chamfered beams with runout stops and planked doors to first floor. Attached to rear are C19 single-storey farm buildings, enclosing a courtyard on three sides. Flemish garden wall bond brick and tiled roofs, planked stable doors and casements.).



©Photo by Mark Geraghty

©Wiltshire OPC Project/2015/Maureen Withey